
PICA CUBE[™] POWER OPTIONS







3M P/N 560 for 18-14AWG Run and Tap 3M P/N 567 for 12-10AWG Run and 18-14AWG Tap

CAT5e

NOTE:

POWER

SUPPLY

Selection of Power Supply and Lead Wire gage dependent on quantity of fixtures installed and distance from Power Supply

www.rosco.com